

TEMPORARY REVISION #2

INSTRUCTIONS

1. This is a Temporary Revision #2 to AAIP inspection A0051.
2. Place this instruction page before Page 2 of A0051.
3. Replace Page 2 of A0051 Temp Rev #2.
4. Replace Page v, Index of Temporary Revisions with Temp Rev-2 Index.

CAUTION: DO NOT REMOVE THIS TEMPORARY UPDATE UNTIL INSTRUCTED TO DO SO AS PART OF:

- A NORMAL UPDATE
- A NEW TEMPORARY REVISION UPDATE SUPERSEDING THIS ONE

DESCRIPTION

1. This revision removes the dynamic balancing requirement of hub and tail rotor from A0051 due to equipment limitations if performed in a remote, field environment. This requirement will now be tracked as a Stand-Alone line item on MHI 407 Series Computer CALM program.

INCORPORATION

Temporary Revision #2 to the Appendix will be incorporated in the 407 AAIP as part of the next normal revision.