Revision: TEMP REV #1
Issue Date: 12/05/17

TEMPORARY REVISION #1

INSTRUCTIONS

1. This Temporary Revision #1 updates the A 1720 inspection.
2. Place this instruction page front of Page 2 of the current A 1720 inspection.
3. Comply with all other inspections of the A 1720 inspection as required.

CAUTION: DO NOT REMOVE THIS TEMPORARY UPDATE UNTIL INSTRUCTED TO DO SO AS PART OF:

- **A NORMAL UPDATE**
- **A NEW TEMPORARY REVISION UPDATE SUPERSEDING THIS ONE**

DESCRIPTION

1. This revision updates the A 1720 inspection by adding additional maintenance requirements should the Oil Cooler Shaft Bearings need replacement.

INCORPORATION

Temporary Revision #1 to the A 1720 inspection Page 2, item 4.6 will be incorporated in the AAIP as part of the next normal revision.