

TEMPORARY REVISION #1

INSTRUCTIONS

1. This Temporary Revision #1 separates out the inspection requirement of A6032RT. Please comply with A6032RT – A6037RT, depending on which component needs to be addressed.
2. Place this instruction page front of each A603X RT inspection.
3. Comply with each inspection as required.

CAUTION: DO NOT REMOVE THIS TEMPORARY UPDATE UNTIL INSTRUCTED TO DO SO AS PART OF:

- A NORMAL UPDATE
- A NEW TEMPORARY REVISION UPDATE SUPERSEDING THIS ONE

DESCRIPTION

1. This revision separates out several individual component inspections that were previously all under A6032RT, but may all be out of sync with the 72 month, do to overhauls and/or replacements.
2. It also addresses all the individual component inspection under the Maintenance Manual MET 05.39.00.601 which is referenced in the Maintenance Program 6 Year inspection under ROTORS 60-00

INCORPORATION

Temporary Revision #1 will be incorporated in the AAIP as part of the next normal revision