

5-12. PROGRESSIVE INSPECTION — EVENT #1

[illegible]

PROGRESSIVE INSPECTIONS

5-12. PROGRESSIVE INSPECTION — EVENT #1 (CONT)

DATA REFERENCE	INSPECTION TASK DESCRIPTION	INITIAL	
		MECH	OTHER
Chapter 53 Chapter 18 Chapter 67 BHT-407-FM-1 or BHT-407-FM-2	b. Inspect tail rotor blades for delamination. c. Inspect pitch links for condition. d. Inspect pitch horns for condition. e. Inspect tailboom for condition in tail rotor blade tip path area.		
	4. Dynamically balance the tail rotor hub and blade assembly.		
	<u>DIRECTIONAL CONTROLS</u>		
	1. Do a torque check of the bolts (60 to 80 inch-pounds (6.7 to 9 Nm)) that attach the tail rotor pitch link assemblies to the tail rotor pitch horns (TB 407-09-88).		
	<u>GROUND RUN</u> 1. Complete a ground run at 100% N_R to check for leaks and confirm system operation.		