

SECTION: A 0301 – AIRFRAME INSPECTION PROGRAM
TYPE: 300 HOUR / 12 MONTH INSPECTION
NOTE:

MAINTENANCE ACTION		REFERENCE	MECHANIC'S INITIALS
9.3	Lubricate tail rotor control lever (three places). Do not intermix grease types. Purge until same grease appears.	Table 12-3 Lubrication Chart	
A 0301.10 POST INSPECTION			
10.1	Replace or close all applicable trim panels, fairings, covers, access and inspection doors/covers as necessary.		
10.2	Complete a ground run at 100% NR to check for leaks and confirm system operation.	BHT-412-FM-2	
10.3	Perform an engine fuel control check.	BHT-412-FM-2	
10.4	Perform Functional Check Flight if required per Bell 412 Maintenance Manual or RFM as appropriate.		
10.5	Make an entry in the appropriate logbook (refer to the following page for wording of approval for return to service).		
10.6	Confirm all required RII have been completed and signed off.		