

Recommended Service Intervals

ITEM		PRE- FLIGHT	100 HOURS	300 HOUR S	12 MONTHS ⁽²⁾
a	Visual inspection of filter element (installed).	•			
b	Inspect, clean, and re-oil filter element. ⁽¹⁾			•	•
c	Inspect and cycle alternate air door.		•		•
d	Inspect differential pressure switch/ warning annunciator components		•		•
e	Inspect electrical connectors.		•		•
f	Inspect attachment hardware, mounting brackets, and inlet ring.			•	•
g	Inspect filter housing structure and associated hardware for cracks and general security.			•	•
h	Leak and pressure test differential pressure switch/annunciator system.				•
i	Inspect and clean Static Port Filter if equipped with Static Port Relocation Kit used with Bell Snow Deflector Kits. ⁽¹⁾			•	•

⁽¹⁾ As required (failed inspection or "LOW INLET PRESSURE" annunciation), 300 hours, or 12 months, **whichever occurs first.**

⁽²⁾ Hours of operation or 12 months, **whichever occurs first.**